BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER: SITE NAME: Copeland Corporation	U.S. ENVIRONMENTAL PROTECTION AGENCY 1997 Hazardous Waste Report						
EPA ID NO: 1101D1 1918151 1717151 1713131	FORM 20 199 DENTIFICATION AND CERTIFICATION MISSOUR DEPARTMENT CO.						
Instructions: Please see the detailed instructions beginning on page 7 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each section is provided below.							
Sec. I Site name and location address. Check the box \square in items A, B absent, enter information. Instructions page 7.	B, C, E, F, G, and H if same as label; if different, enter corrections. If label is						
A. EPA ID No. Same as label □ or → [M O D 9 8 5 17 7 15 17 13 3 Same as label □ or → Laclede							
C. Site/company name Same as label □ or → Copeland Corporation	D. Has the site name associated with this EPA ID changed since 1995? □ 1 Yes						
E. Street name and number. If not applicable, enter industrial park, building name, or other physical location description. Same as label □ or → 701 East Highway 32							
F. City, town, village Same as label □ or → Lebanon	G. State Same as label □ or →						
Sec. II Mailing address of site. Instructions page 7.	XX						
A. Is the mailing address the same as the location address? B. Number and street name of mailing address P.O. Box	s (SKIP TO SEC. III) XX2 No (CONTINUE TO BOX B) 1152						
C. City, town, village Lebanon	D. State E. Zip Code 6 5 5 3 6 - 1 1 5 2						
Sec. III Name, title, and telephone number of the person who should be	be contacted if questions arise regarding this report. Instructions page 7.						
A. Last Name First name M.I. Bair Tim L.	B. Title Environmental Coordinator C. Telephone Number 4 11 7 5 8 8 - 8 6 1 8 Extension						
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties under Section 3008 of the Resource Conservation and Recovery Act for submitting false information, including the possibility of fine and imprisonment for knowing violations." Instructions page 8.							
A. Last Name First name M.I. Rose Robert R.	B. Title Director North America Scroll Operations						

R00115848

ENT'D MAY 1 8 1998

D. Date of signature

021181918 Day

Month

Year

Over

EPA ID NO. [M101D] (91815) (71715) (71313)

Sec. V Generator status. Instruct	Generator status. Instructions begin on page 8.							
A. 1997 RCRA generator status	B. Reason for not generating	-						
(CHECK ONE BOX BELOW)	(CHECK ALL THAT APPLY)							
LQG □ 2 SQG □ 3 CESQG □ 4 Non-generator (CONTINUE TO BOX	□ 1 Never generated □ 2 Out of business □ 3 Only excluded or delisted B) □ 4 Only non-hazardous waste		□ 5 Periodic or occasional generator □ 6 Waste minimization activity □ 7 Other (SPECIF IN COMMENTS BOX BELOW)					
Sec. VI On-site waste managemen	status. Instructions page 10.		A					
A. Storage subject to RCRA permitting	eatment, disposal, or recycling subject to RCRA permitting ements							
للا		1						
Comments:								

	BEFORE ENTER: SITE NA	ME: Copeland Corporation	OUNTED STATES.	U.S. ENVIRONMENTAL PROTECTION AGENCY 1997 Hazardous Waste Report					
	EPA ID I	vo: LMLOLDI L9L8L5I L7L7L5I L7L3I	FORM WASTE GENERATION AND MANAGEMENT						
	Instruc comple	tions: Please see the detailed instruction eting this form. In addition, the page num	ns beginning on pa ber for instruction	age 11 of the instr as specific to each	uctions and forms booklet before box is provided in parentheses.				
	Sec. I A. Waste description (page 12) Corrosive Spent Sodium Hydroxide From De-Rust Operations.								
	B. EPA (page 12	hazardous waste code <u>DDDD2</u>	V∕A V∕A	C. State hazardous waste code (page 13)					
n n	D. SIC (page 13	2. S.ig.ii 5545	F. Source code (page 14)	measurement (p	I. RCRA-radioactive mixed age 14) (page 14)				
	Sec. II	A. Quantity generated in 1997 (page 15) Lilianianianianianianianianianianianianiani	15) /	C. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? (page 15) 1 Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1) XX2 No (SKIP TO SEC. III)					
		PROCESS SYSTEM 1 process system type On site in 1997 (page 1		On-site process system type (page 16) On-site process system type on site in 1997 (page 16)					
	Γw		ш.Ц	L™1111.					
	Sec. III A. Was any of this waste shipped off site in 1997 for treatment, disposal, or recycling? (page 17) XX Yes (CONTINUE TO BOX B) □ 2 No (FORM IS COMPLETE)								
	Site 1	B. EPA ID No. of facility waste was shipped to (page 17)	C. System type shipped to (p. 17)	D. Off-site availability code (page 17)	E. Total quantity shipped in 1997 (page 17)				
	Site 2	B. EPA ID No. of facility waste was shipped to (page 17)	C. System type shipped to (p. 17)	D. Off-site availability code (page 17)	E. Total quantity shipped in 1997 (page 17)				
	Site 3	B. EPA ID No. of facility waste was shipped to (page 17)	C. System type shipped to (p. 17)	D. Off-site availability code (page 17)	E. Total quantity shipped in 1997 (page 17)				
× 4	Comme	nts:	х						

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER: SITE NAME: Copeland Corporation					Charles STATES ON SON ASSESSED TO SON ASSESSED	U.S. ENVIRONMENTAL PROTECTION AGENCY 1997 Hazardous Waste Report		
EPA II		DI 1 <u>91815</u> 117151		· ·	FORM GM	AND	TE GENERATION MANAGEMENT	
Instru comp	uctions: Please pleting this form	e see the detailed ins n. In addition, the pa	truction ge numl	s beginning on pa ber for instruction	age 11 of the ins	structions and ch box is prov	forms booklet before ided in parentheses.	
Sec. I		cription (page 12)	ution	From Coatings	s I.ah Mest			
	Toxic Spent Chromium Solution From Coation EPA hazardous waste code DOO TO LN/AL Sage 12) N/AL N/AL LN/AL				C. State hazardous waste code (page 13)			
D. SI (page	C code 13) <u>3, 5, 8, 5</u> ,	E. Origin code 11 (page 13) System	n Type	F. Source code (page 14)	G. Point of measurement (p. 14)	H. Form code (page 14)	I. RCRA-radioactive mixed (page 14)	
Sec.	A. Quantity generated in 1997 (page 15) B. UOM [1] (page 15) Density [1] 1 lbs/gal 2 sg			5)	C. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? (page 15) 1 Yes (CONTINUE TO ON-SITE PROCESS SYSTEM 1)			
On-si	n-site process system type age 16) Quantity treated, disposed, or recycled on site in 1997 (page 16)				On-site process system type (page 16) On-site process system type on site in 1997 (page 16)			
	[M]				[M]			
Sec.	III A. Was any o	f this waste shipped off site (CONTINUE TO BOX B)	e in 1997 □ 2	for treatment, dispos No (FORM IS COMF	al, or recycling? (pa PLETE)			
Site	(page 17)	o. of facility waste was ship		C. System type shipped to (p. 17)	D. Off-site availat code (page 17)		uantity shipped in 1997 (page 1	
Site	(page 17)	o. of facility waste was ship	•	C. System type shipped to (p. 17)	D. Off-site availal code (page 17)	1	uantity shipped in 1997 (page 1	
Site	(page 17)	o. of facility waste was ship		C. System type shipped to (p. 17)	D. Off-site availal code (page 17)		uantity shipped in 1997 (page 1	
Com	ments:							

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

SITE NAME: Copeland Corporation

EPA ID NO: LMI OI DI L918151 L717151 L713131



U.S. ENVIRONMENTAL PROTECTION AGENCY

1997 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

Instructions: Please see the detailed instructions beginning on page 11 of the instructions and forms booklet before completing this form. In addition, the page number for instructions specific to each box is provided in parentheses.

Sec. I	A. Waste description (page 12)								
	Toxic Waste	Mercury Cont	ght Tubes.	.*					
B. EPA hazardous waste code _D\O\O\9\ _\N				C. State hazardous waste code (page 13)		ge 13)			
(page 12) INVAL LINVAL NVA									
1		E. Origin code 1 (page 13) System Type		F. Source code (page 14) - [A]9]9]	G. Point of measurement (p. 14)	H. Form code (page 14) L ^B J 71 OI 1J	I. RCRA-radioactive mixed (page 14)		
Sec. II A. Quantity general (page 15)		B. UOI (page 1		5)	C. Did this site do any of the following to this waste: tred dispose on site, recycle on site, or discharge to a sewer (page 15)				
				1 lbs/gal □ 2 sg	☐ 1 Yes (CONTINU ☐ 2 No (SKIP TO S	JE TO ON-SITE F SEC. III)	PROCESS SYSTEM 1)		
ON-SITE PROCESS SYSTEM 1				ON-SITE PROCESS SYSTEM 2					
On-site process system type (page 16) Quantity treated, dispose on site in 1997 (page 16)				On-site process system type (page 16) Quantity treated, disposed, or recycled on site in 1997 (page 16)					
[M]			ш.	[MIII] [1111111111111111111111111111111111					
Sec. III	Sec. III A. Was any of this waste shipped off site in 1997 for treatment, disposal, or recycling? (page 17) XXI Yes (CONTINUE TO BOX B) □ 2 No (FORM IS COMPLETE)								
Site 1	The second control of the second of the seco	cility waste was ship	oed to	C. System type	D. Off-site availability E. Total qual code (page 17)		uantity shipped in 1997 (page 17)		
	(page 17) [PIAID] [91817] [31617] [21116]		shipped to (p. 17) [M] 0 1 9	Lode (page 17)		1 1 1 1615151.0			
Site 2	Site 2 B. EPA ID No. of facility waste was shipped to (page 17)		C. System type shipped to (p. 17)	D. Off-site availab	cility E. Total qu	uantity shipped in 1997 (page 17)			
			L _M	L		<u></u>			
Site 3 B. EPA ID No. of facility waste was shipped to			C. System type shipped to (p. 17)	D. Off-site availat	cility E. Total q	uantity shipped in 1997 (page 17)			
(page 17)			L						

Comments:

Section I; Box F: Replacement of Burned Out Fluorescent Light Tubes.

Section III; Box C: Mercury Vapor is Extracted From Fluorescent Light Tubes & Recycled.